

NAVAL SAFETY CENTER
NAVAL AIR STATION
NORFOLK, VIRGINIA 23511

14/ras
Ser 986
15 Aug 1968

SPECIAL HANDLING REQUIRED IAW OPNAVINST 3750.6 SERIES
[REDACTED]

From: Commander, Naval Safety Center
To: Commanding Officer, Training Squadron THREE

Subj: VT-3 AAR ser 5-68A concerning T-28B's BuNo's 137730/140052
accident occurring 20 May 1968, pilots (b) (6) KINDERMAN

1. The subject report and all endorsements thereon have been reviewed.
Commander, Naval Safety Center concurs with the comments and recommendations of the Aircraft Accident Board as modified by subsequent endorsers.

(b) (5)
[REDACTED]

(b) (5)
[REDACTED]

By direction

Copy to:
NAVAIRSYSCOMHQ (AIR 09E) (2)
CNATRA
CNABATRA
NAVPLANTREPO COLUMBUS
CO NAVAERORECOVPAC
DIR AFIP

[REDACTED]

Code 015

8 JUL 1968

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST
3750.6 SERIES

THIRD ENDORSEMENT on CO, VT-3, accident, Ser 5-68A, concerning T-28B, BUNO 137730 and T-28B, BUNO 140052, of 20 May 1968, pilots (b) (6) and KINDERMAN

From: Chief of Naval Air Training
To: Commander, Naval Safety Center

Subj: Aircraft accident report; forwarding of

1. Forwarded, concurring in the conclusions and recommendations of the Aircraft Accident Board and comments and action indicated in the subsequent endorsements.

F. J. Moore, Jr.
F. J. MOORE, Jr.
Chief of Staff

Copy to:
CNABATRA
COMNAVAIRSYSCOM (AIR 404)
NAVAIRSYSCOM, NAVPLANTREPO, Columbus
DIR, AFIP
CO, NAVAERORECOVFAC, El Centro
CO, TRARON THREE

Code 015

25 JUN 1968

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6
SERIES

SECOND ENDORSEMENT on TRARON THREE, accident, serial 5-68A
concerning T-28B, BuNo 137730, of 20 May 1968, pilots (b) (6)
KINDERMAN

From: Chief of Naval Air Basic Training
To: Commander, Naval Safety Center
Via: Chief of Naval Air Training

Subj: Aircraft Accident Report; forwarding of

1. Forwarded concurring in the conclusions and recommendations
of the Aircraft Accident Board and with the comments and correc-
tive actions initiated by the Commanding Officer, Training
Squadron THREE.

(b) (5)

Copy to:
NAVSAFECEN (2 direct)
NAVAIRSYSCOM (AIR 404)
CNATRA
NAVPLANTREPO COLUMBUS
DIRAFIP
CO, NAVAERREC FAC
CO, TRARON THREE



D. H. GUINN

Code AD
JUN 4 1968

FIRST ENDORSEMENT on TRACON THREE AAR Ser 5-68a concerning T-28B BUNO
140052 Pilot ENS G. L. KINDERMAN, USNR and T-28B BUNO 137730 Pilot ENS
(b) (6) USN, occurring 20 May 1968

From: Commanding Officer, Training Squadron THREE
To: Commander, Naval Aviation Safety Center
Via: (1) Chief of Naval Air Basic Training
(2) Chief of Naval Air Training

Subj: Aircraft Accident Report; forwarding of

1. Forwarded, concurring with the conclusions and recommendations of
the Aircraft Accident Board subject to the following comments.

(b) (5)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAV INST 3750.6 SERIES

Code AD

JUN 14 1968

Subj: Aircraft Accident Report; forwarding of

(b) (5)



L. E. Brumbach
L. E. BRUMBACH

Copy to:

1CC NAVAIRSYSCOM (AIR 404)

1CC CNATRA

1CC CNABATRA

1CC NAVPLANTREPO COLUMBUS

1CC DIRAFIP

1CC CO NAVAERREC PAC

2CC NAVAVNSAPCEN DIRECT (AAR)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAV INST 3750.6 SERIES

AIRCRAFT ACCIDENT REPORT

OPNAV FORM 3750-1A (Rev. 3-63) Page 2

SPECIAL HANDLING REQUIRED in accordance with

Para. 65, OPNAV INSTRUCTION 3750.6, effective edition

OPNAV REPORT 3750-1

140052

PART II MAINTENANCE, MATERIAL AND FACILITIES DATA									
1. DATE OF MANUFACTURE	2. FLIGHT HRS SINCE ACCEPTANCE	3. NO. OF PAR/OVERHAUL	4. MONTHS SINCE LAST PAR/OVERHAUL	5. FLT. HRS SINCE LAST PAR/OVERHAUL	6. LAST/PAR OVERHAUL ACTIVITY	7. TYPE OF LAST CHECK PERFORMED	8. FLIGHT HOURS SINCE LAST CHECK	9. DAYS SINCE LAST CHECK	
24 FEB 1956	65064	4	27	1749.5	PNCLA	Calendar	35.4	26	

1. ENGINE MODEL	2. ENGINE SERIAL NUMBER	3. FLIGHT HRS SINCE ACCEPTANCE	4. NUMBER OF OVERHAULS	5. WAS DIR REQUESTED?	6. FLT. HRS SINCE LAST OVERHAUL	7. LAST OVERHAUL ACTIVITY	8. TYPE OF LAST CHECK PERFORMED	9. FLIGHT HOURS SINCE LAST CHECK	10. DAYS SINCE LAST CHECK
(1) R18	BL520								
20-86A	774	5322	7	NO	97.7	PNCLA	Calendar	35.4	26
(2)									
(3)									
(4)									

1. COMPONENT INVOLVED NOMENCLATURE	2. MANUFACTURERS PART NUMBER	3. TOTAL HRS ON PART	4. NO. OF OVERHAULS	5. HOURS SINCE LAST OVERHAUL	6. OVERHAUL ACTIVITY	7. WAS DIR REQUESTED?	8. SER. NO. FOR ADDRESS
(1)							
(2)							
(3)							
(4)							

1. PARTS REPAIRED			2. PARTS REPLACED	
PART NUMBER	NOMENCLATURE	3. DIRECT MANHOURS INVOLVED	PART NUMBER	NOMENCLATURE

JET ENGINE FLAMEOUT (Include intentional securing to prevent engine damage)									
AT TIME OF FLAMEOUT	1. ALTITUDE	2. IAS	3. RPM	4. EGT	5. MANEUVER AT TIME OF FLAMEOUT	6. FUEL FLOW	7. ATTITUDE	8. G FORCES	9. RELIGHT
									<input type="checkbox"/> ATTEMPTED <input type="checkbox"/> ACCOMPLISHED
	10. ALTITUDE	11. IAS	12. MAX EGT	13. FUEL CONTROL	14. NO RELIGHT ATTEMPTS				
				<input type="checkbox"/> PRIMARY <input type="checkbox"/> MANUAL					
INTENTIONAL SECURE	15. ENGINE SYMPTOMS			16. CAUSE OF SYMPTOMS					

RECIPROCATING ENGINE FAILURE							
17. ALTITUDE	18. IAS	19. ATTITUDE	20. RPM	21. MAP	22. TORQUE/BMEP	23. FUEL FLOW PRESSURE	24. OIL PRESSURE
INTENTIONAL SECURE	25. ENGINE SYMPTOMS			26. CAUSE OF SYMPTOMS			

F. OTHER REPORT	
IDENTIFY OTHER REPORTS CONCERNING THIS MISHAP	
1. AMPFUR SERIAL NUMBER	NA
2. DIR MESSAGE REQUEST DATE-TIME-GROUP	
3. OTHER	Preliminary / Supplementary Msg 202044 2 May
4. Request for Engineering Analysis	241840 3 May 68

AIRCRAFT ACCIDENT REPORT

SPECIAL HANDLING REQUIRED *is member*

OPNAV REPORT 3750-1A

OPNAV FORM 3750-1A (Rev. 3-63) Page 3

Para. 66, OPNAV INSTRUCTION 3750.6, effective edition

1. EQUIPMENT INVOLVED <input type="checkbox"/> CATAPULT <input type="checkbox"/> ARRESTING GEAR		2. PRESSURE SETTING		3. WIND OVER DECK		4. RELATIVE WIND		5. APPROACH/END SPEED	
6. MARK NUMBER		7. MODEL NUMBER		8. LOCATION OF SHIP		9. LAUNCHING BRDLE AND BRDLE ARRESTER			
10. CATAPULT/ARRESTING GEAR BULLETINS OR NONCOMGRAMS USED									
11. This portion shall be completed whenever (1) an aircraft accident involves arresting gear barrier and/or barricade equipment, or (2) an aircraft accident involves malfunctioning of arresting gear, barrier and/or barricade equipment. Incidents or routine damage to cables, weldings and other expendable equipment need not be reported herein.									
G. SHIPS DATA	ENGAGED	12. DECK RUNOUT (FEET)	13. RAM TRAVEL (INCHES)	14. CONTROL VALVE SETTINGS CONSTANT PRESSURE DOMESTIC (P.S.I.) RATIO		15. ACCUMULATOR PRESSURE (PSI)	16. COMMENTS (for cable failures specify no. landings and months in service)		
	DECK PENDANT								
	DECK PENDANT								
	BARRIER/BARRICADE								
H. DEPLOYMENT	FOR ACCIDENTS ABOARD CARRIERS (complete on pilot)								
	1. DATE DEPLOYED COMUS		3. DAY HOURS/LANDINGS SINCE DEPLOYMENT			4. DAY HOURS/LANDINGS LAST 30 DAYS			
	2. NO. DAYS OPERATING PERIOD		6. NIGHT HOURS/LANDINGS SINCE DEPLOYMENT			7. NIGHT HOURS/LANDINGS LAST 30 DAYS			
	5. INST. HOURS LOGGED SINCE DEPLOYMENT ACTUAL/SIMULATED								
I. WEATHER	WEATHER AT SCENE OF MISHAP								
	1. CEILING	2. VISIBILITY	3. RELATIVE WIND DIRECTION AND VELOCITY		4. TEMPERATURE SURFACE OUTSIDE AIR	5. DEW POINT	6. ALTIMETER SETTING		
	CLEAR	+ 15	330/11		73° F	46° F	29.88		
	7. OTHER WEATHER CONDITIONS (clouds, fog, icing, hail, etc., density, etc., as appropriate)								
NONE									

PART III ADDITIONAL INFORMATION			
PART	SECTION	ITEM	1. REMARKS
			2. COPY DISTRIBUTION 20C NAVJAGSAFEEN DIRECT (AM) 15C-OPS BUREAU BUREAU ***** ICC NAVAIRSYS COM (AIR404) ICC CNATRA ICC CNABATRA ICC NAVPLANTREPO COLUMBUS ICC DIRAFIP ICC CO NAVAEHREC 5. DATE SUBMITTED TO GO PAC 8 JUN 1968
COST DAMAGE TO:		3. GOVERNMENT PROPERTY	4. PRIVATE PROPERTY
		NONE	NONE

PART IV SIGNATURES OF THE BOARD			
1. SENIOR MEMBER	2. MEMBER	3. MEMBER	4. MEMBER
USN Aircraft Division Officer UNIT BILLET	USN Officer VT-3 UNIT BILLET	USN Officer (UNIT 2) UNIT BILLET	

When preparing Incident and Ground Accident reports, items indicated by an asterisk (*) must be filled in. Other items considered appropriate should also be filled in.

Mem (b) (6)

LT.

Maintenance Quality Control Officer

AIRCRAFT ACCIDENT REPORT

OPNAV FORM 3750-1A (Rev. 3-63) Page 1

SPECIAL HANDLING REQUIRED in accordance with

Para. 66, OPNAV INSTRUCTION 3750.6, effective edition

OPNAV REPORT 3750-1

PART 1 GENERAL

SECTION A. IDENTIFICATION

1. AIRCRAFT ACCIDENT BOARD APPOINTED BY TRACON THREE COMMANDING OFFICER	2. SERIAL NO. 5-68A	3. DTG LOGAL OF MISHAP 201100S	4. MODEL AIRCRAFT T-28B	5. BUREAU NUMBER 132230
6. TO: Commander, Naval Aviation Safety Center	7. VIA C.O. TRACON THREE	8. 9. LOCATION OF MISHAP 340° Radial 20 mi. TACAN	10. DAMAGE ALFA	11. FLIGHT CODE 1 D 1
12. CNAATRA	13. CNAATRA	14. CLEARED FMAS Whiting	15. TYPE CLEARANCE Local VFR	16. AIRSPEED 160 IAS
17. TO: NAAS Whiting	18. BRIEF DESCRIPTION OF MISHAP Mid-air collision during syllabus/Flight	19. ELEVATION AT TIME OF MISHAP 3500	20. TERRAIN 3400	21. LIST MODEL, BUND, REPORTING CUSTODIAN AND DAMAGE CLASSIFICATION OF ANY OTHER A/C INVOLVED (Complete OPNAV Form 3750-1 for each A/C)
T-28B, 140052, VT-3 ALFA				

(b) (5)

PILOT (at controls at time of mishap)	ENS	(b) (6)	USN	23	N/A	SNA	P/C	"B"
CO-PILOT (Identify & submit separate page 1)	4796161							
ITEM		ITEM						
11. ALL MODELS	108	17. CV LANDINGS DAY/NIGHT	ALL	0/				
12. ALL MODELS IN LAST 12 MONTHS	108	18. FOLP LANDINGS LAST 6 MONTHS DAY/NIGHT	ALL	0/				
13. ALL MODELS IN LAST 3 MONTHS	81	19. INSTRUMENT HOURS LAST 3 MONTHS ACTUAL/SIMULATED	ALL	1/26				
14. ALL SERIES THIS MODEL	A/C 81	20. NIGHT HOURS LAST 3 MONTHS	ALL	6/				
15. ALL SERIES THIS MODEL LAST 12 MONTHS	OFT/CPT 81	21. TOTAL HOURS IN JETS (if jet mishap) HELOS (if helo mishap)	IN MODEL	1/26				
16. ALL SERIES THIS MODEL LAST 3 MONTHS	A/C 81	22. LAST PRIOR FLIGHT ALL SERIES THIS MODEL	DATE	17 MAY 68				
17. DATE/GUIDE LAST NATOPS STANDARDIZATION CHECK	N.A.	23. DURATION	2					
24. TYPE INSTRUMENT CARD		NONE						
25. NAME (Last, First, & middle initial)	26. GRADE	27. BRANCH OF SERVICE	28. TYPE	29. UNIT	30. INJURY	31. RELAT	32. POSITION	

OP-151

AIRCRAFT ACCIDENT REPORT

OPNAV FORM 3750-1A (Rev. 3-63) Page 2

SPECIAL HANDLING REQUIRED in accordance with

Para. 66, OPNAV INSTRUCTION 3750.6, effective edition

OPNAV REPORT 3750-1

137730

PART II MAINTENANCE, MATERIAL AND FACILITIES DATA

A. AIRCRAFT HISTORY									
1. DATE OF MANUFACTURE	2. FLIGHT HRS. SINCE ACCEPTANCE	3. NO. OF PAR/OVERHAUL	4. MONTHS SINCE LAST PAR/OVERHAUL	5. FLT HRS SINCE LAST PAR/OVERHAUL	6. LAST PAR/OVERHAUL ACTIVITY	7. TYPE OF LAST CHECK PERFORMED	8. FLIGHT HOURS SINCE LAST CHECK	9. DAYS SINCE LAST CHECK	
10 MAY 1954	8050.7	4	12	896.6	PNCL	Special	46.5	17	
B. ENGINE HISTORY									
1. ENGINE MODEL	2. ENGINE SERIAL NUMBER	3. FLIGHT HRS. SINCE ACCEPTANCE	4. NUMBER OF OVERHAULS	5. WAS DIR. REQUESTED?	6. FLT HRS SINCE LAST OVERHAUL	7. LAST OVERHAUL ACTIVITY	8. TYPE OF LAST CHECK PERFORMED	9. FLIGHT HOURS SINCE LAST CHECK	10. DAYS SINCE LAST CHECK
WR18	BL520	5331.7	6	NO	509.9	PNCL	SPECIAL	46.5	17
(2)									
(3)									
(4)									
C. COMPONENT HISTORY									
1. COMPONENT INVOLVED NOMENCLATURE	2. MANUFACTURER'S PART NUMBER	3. TOTAL HRS. ON PART	4. NO. OF OV. HAULS	5. HOURS SINCE LAST OVERHAUL	6. OVERHAUL ACTIVITY	7. WAS DIR. REQUESTED?	8. SER. NO. FOR AMPLEUR		
(1)									
(2)									
(3)									
(4)									
D. INCIDENTS & GROUND ACCIDENTS									
1. PARTS REPAIRED				2. PARTS REPLACED					
PART NUMBER		NOMENCLATURE		3. DIRECT HAN HOURS INVOLVED		PART NUMBER		NOMENCLATURE	
E. ENGINE FAILURES									
JET ENGINE FLAMEOUT (Include intentional securing to prevent engine damage)									
AT TIME OF FLAMEOUT	1. ALTITUDE	2. IAS	3. RPM	4. EGT	5. MANEUVER AT TIME OF FLAMEOUT	6. FUEL FLOW	7. ALTITUDE		
8. G FORCES	9. RELIGHT	10. ALTITUDE		11. IAS	12. MAX EGT	13. FUEL CONTROL	14. NO. RELIGHT ATTEMPTS		
	<input type="checkbox"/> ATTEMPTED <input type="checkbox"/> ACCOMPLISHED					<input type="checkbox"/> PRIMARY <input type="checkbox"/> MANUAL			
INTENTIONAL SECURE	15. ENGINE SYMPTOMS				16. CAUSE OF SYMPTOMS				
RECIPROCATING ENGINE FAILURE									
17. ALTITUDE	18. IAS	19. ALTITUDE	20. RPM	21. MAP	22. TORQUE/BHP	23. FUEL FLOW PRESSURE	24. OIL PRESSURE		
INTENTIONAL SECURE	25. ENGINE SYMPTOMS				26. CAUSE OF SYMPTOMS				
F. OTHER REPORT									
IDENTIFY OTHER REPORTS CONCERNING THIS MISHAP									
1. AMPLEUR SERIAL NUMBER <u>N/A</u>									
2. DIR MESSAGE REQUEST DATE-TIME-GROUP <u></u>									
3. OTHER <u>Preliminary / Supplementary Msg 202044 8 May</u>									
4. Request for Engineering Analysis 241840 8 May 68									

AIRCRAFT ACCIDENT REPORT

OPNAV FORM 3750-1A (Rev. 3-63) Page 3

SPECIAL HANDLING REQUIRED in accordance with

Para. 46, OPNAV INSTRUCTION 3750.6, effective edition

OPNAV REPORT 3750-1

1. EQUIPMENT INVOLVED <input type="checkbox"/> CATAPULT <input type="checkbox"/> ARRESTING GEAR		2. PRESSURE SETTING		3. WIND OVER DECK		4. RELATIVE WIND		5. APPROACH/END SPEED	
6. MARK NUMBER		7. MODEL NUMBER		8. LOCATION OF SHIP		9. LAUNCHING (SHOULDER AND GROUND) ARRESTER			
10. CATAPULT/ARRESTING GEAR PULLETS OR NONOCHROMS USED									
11. This portion shall be completed whenever (1) an aircraft accident involves arresting gear barrier and/or barricade equipment or (2) an aircraft accident involves malfunctioning of arresting gear, barrier and/or barricade equipment. Incidents or routine damage to cables, weldings and other expendable equipment need not be reported herein.									
G. SHIPS DATA	ENGAGED	12. DECK RUNOUT (FEET)	13. RAM TRAVEL (INCHES)	14. CONTROL VALVE SETTINGS CONSTANT PRESSURE DOSE (P.S.I.) RATIO		CONSTANT RUNOUT (WT. LBS.)	15. ACCUMULATOR PRESSURE (PSI)	16. COMMENTS (for cable failures specify no. landings and months in service)	
	DECK PENDANT								
	DECK PENDANT								
	BARRIER/BARRICADE								
H. DEPLOYMENT	FOR ACCIDENTS ABOARD CARRIERS (complete on pilot)								
	1. DATE DEPLOYED COMUS			3. DAY HOURS/LANDINGS SINCE DEPLOYMENT			4. DAY HOURS/LANDING LAST 30 DAYS		
	2. NO. DAYS OPERATING PERIOD								
	5. INST. HOURS LOGGED SINCE DEPLOYMENT ACTUAL/SIMULATED			6. NIGHT HOURS/LANDINGS SINCE DEPLOYMENT			7. NIGHT HOURS/LANDINGS LAST 30 DAYS		
I. WEATHER	WEATHER AT SCENE OF MISHAP								
	1. CEILING	2. VISIBILITY	3. RELATIVE WIND DIRECTION AND VELOCITY		4. TEMPERATURE RUNWAY OUTSIDE AIR	5. DEW POINT	6. ALTIMETER SETTING		
	CLEAR	+ 15	330/11		72 F	46° F	29.88		
	7. OTHER WEATHER CONDITIONS (include alt. icing level, sea state, density altitude as appropriate)								
NONE									

PART III ADDITIONAL INFORMATION

PART	SECTION	ITEM	1.	REMARKS	2.	COPY DISTRIBUTION
						ICC NAVYNSAFECN DIRECT (AAR)
						ICC NAVAIRSYS.COM (AIR404)
						ICC CNATRA
						ICC CNABATRA
						ICC NAVPLANTREPO COLUMBUS
						ICC DIB AFIP
						ICC CO NAVABREC
COST DAMAGE TO:			3. GOVERNMENT PROPERTY	4. PRIVATE PROPERTY	5. DATE SUBMITTED TO CO	PAC
			NONE	NONE	8 JUNE 1968	

PART IV SIGNATURES OF THE BOARD

1. SENIOR MEMBER	LCDR (b) (6)	USN	2. MEMBER	(b) (6)	VT-3
Aircraft Division Officer					
3. FLIGHT SQUAD	(b) (6)	UNIT BULLET	4. MEMBER	(b) (6)	UNIT BULLET
		(MC)			
			USN		
			Aviation Safety Officer (AVASO)		
* When preparing incident and ground Accident reports, items indicated by an asterisk must be filled in. Other items considered appropriate should also be filled in.					
		LT.	USN		
		Maintenance Quality Control Officer			

PART V THE ACCIDENT

A. On Monday, 20 May 1968, a flight of three aircraft, two flown by student aviators and the other by an instructor chase pilot were scheduled for a formation training flight. The students were briefed by the chase pilot and then departed. ENS. KINDERMAN was assigned BUNO 140052 (side number 2W 234). ENS. (b) (6) was assigned BUNO 137730 (side number 2W 243). LT. (b) (6) the instructor chase pilot and ENS. (b) (6) passenger were in BUNO 137742 (side number 2W 242).

B. Following normal start, taxi and run-up, the flight took off at 0955 with ENS. (b) (6) as leader in 243, ENS. KINDERMAN as wingman in 234, LT. (b) (6) as chase pilot in 242. Climb out to 3,500 feet and the first sequence with ENS. (b) (6) as leader was uneventful.

C. After the lead change, ENS. KINDERMAN in 234 was the leader and ENS. (b) (6) in 243 was the wingman. During the second turn to the right in the free cruise turn series, the wingman developed an excessive nose to tail closure rate. Therefore, the wingman, ENS. (b) (6) in 243 commenced an under-run by shallowing his angle of bank. The wingman passed under the leader and out to the port side. At this time the leader leveled his wings commencing his rollout on a heading of North

Page 4

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAV INST 3750.6 SERIES.

and the two aircraft came in contact.

D. ENS. (b) (6) aircraft 243 exploded, burst into flames
and broke into two sections. ENS. (b) (6) with some difficulty
was able to clear his aircraft and successfully parachuted,
landing in a wooded area. ENS. KINDERMAN in 234 was observed
in a low descending right hand turn with the canopy closed
and was found in the wreckage.

E. The chase pilot immediately broadcast the crash and SAR
units responded. (Enclosure 9) ENS. (b) (6) pilot of 243,
was picked up by helicopter and taken to the Whiting Field
dispensary.

Page 5

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAV INST 3750.6
SERIES.

PART VI DAMAGE TO AIRCRAFT

- A. Both aircraft received strike damage. ENS. (b) (6) aircraft BUNO 137730 (side number 2W 243) exploded upon contact with lead aircraft. The explosion was at the port wing root at fuselage stations 113-136. The aircraft broke in two pieces and burned (Enclosures 5 and 8). The port wing flap and port horizontal stabilizer were not located.
- B. ENS. KINDERMAN's aircraft BUNO 140052 (side number 234) received strike damage upon impact with the ground.

Engine Section. The engine was separated from the airframe on impact.

Wings. The port wing was attached to the fuselage. The starboard wing separated from the aircraft due to contact with a tree.

Fuselage. Empennage was separated from the fuselage on impact with trees and ground. Refer to (Enclosures 6 and 7).


- C. The center of impact BUNO 140052 (side number 2W 234) was located in dense, swampy undergrowth in a heavily wooded area. The mud crater created by impact filled with water in a matter of hours. Due to the swampy ground and dense forest it was not considered feasible by the Board to attempt to remove the aircraft. (Enclosure 10).

Page 6

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAV INST 3750.6 SERIES.

PART VII INVESTIGATION AND ANALYSIS

(b) (5), (b) (6)



Investigation of the wreckage of ENS. (b) (6) aircraft
BUNO 137730 (side number 2W 243) revealed the following facts.

1. The propeller of ENS. (b) (6) aircraft 243 did not
strike the lead aircraft as evident by the absence of marks on
the propeller. (Enclosure 4).

2. The front cockpit canopy of ENS. (b) (6) aircraft 243
did not come in contact with the lead aircraft as evident by
the absence of marks on the canopy.

Page 7

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAV INST 3750.6
SERIES.

3. The inflight explosion just after the mid-air collision occurred between fuselage stations 113-136, probably the port wing main fuel line. The engine and cowling of 243 received no inflight damage. (Enclosures 4 and 5)

4. The port horizontal stabilizer was torn away prior to the fire. A search by ground crews and helicopter could not locate the missing port wing flap or horizontal stabilizer. It is suspected that these sections buried themselves in the swampy terrain upon impact.

5. The wing aircraft 243 sustained initial contact behind the pilot's canopy and at the port wing root just forward of the flap, causing separation of the port wing flap and extending the port main gear prior to the explosion and fire. There is no evidence of fire on the port main tire. The propeller damage by 234 also caused 243 to break into two sections.

Investigation of the wreckage of ENS KINDERMAN's aircraft BUNO 140052 (side number 2W 234). (Enclosures 6 and 7)

1. All control surfaces were attached to the aircraft upon impact.

2. There is no evidence of any fire or explosion prior to or after impact with the ground.

(b) (5)

Page 8

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAV INST 3750.6 SERIES.

(b) (6)

4. At some point after the mid-air collision and prior to impact with the ground SFS. KUNDERMAN attempted to egress. This is evident by his seat belt being undone and found to be wedged down and under the seat after impact.

5. The canopy tracks and trucks indicated 60% open, however, the main canopy actuating cylinder was fully open at impact.

6. Investigation of the canopy system revealed the following:

a. The emergency system was not used to open the canopy. The canopy system was full of hydraulic fluid. The canopy actuating cylinder was full of fluid and open.

b. The canopy emergency air pressure system was intact upon impact with 2000# of pressure at impact.

c. All canopy valves, emergency air components and actuating cylinder were submitted for engineering analysis. Telephone conversation report indicates all components were functioning normally.

7. The engine and accessory section were buried from sight in a hole of mud and water eight (8) feet deep.

8. It is estimated that the aircraft was in a 65° dive with 15° angle of bank to the right upon impact.

Page 9

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAV INST 3750.6 SERIES.

A. Personnel Factors


(b) (5), (b) (6)



Page 10

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OFFAV INST 3750.6
SERIES.


(b) (5), (b) (6)



Page 11

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OFMAV INST 3750.6
SERIES.

(b) (5), (b) (6)



Page 12

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAV INST 3750.6
SERIES.

(b) (5)



Page 13

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAV INST 3750.6
SERIES.

PART IX RECOMMENDATIONS

(b) (5)



Page 14

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OFNAV INST 3750.6
SERIES.